

Diamond Coated Grippers For A Longer Gripping Life.
Lower Cost **GT Specialties** **Better Gripper**

2901-A Edith Blvd. NE, Albuquerque. New Mexico USA 87107
 Ph# 505-343-0600 e-mail: Sales@gt-specialties.com Fx# 505-343-0606

Reconditioning

We recondition your MO, S-line and Speed Master In-Feed Ranger aluminum gripper pad bar with a new diamond gripping surface. Our normal time for recondition your gripper bar will be within five working days or sooner.





fig. 1

Upon receiving a bar, we inspect the bar for straightness and the location of each pad surface and then inform our customer of our findings. (fig.1)

Going forward in reconditioning the gripper bar, we remove the old gripping surface and machining all the pad surfaces at the same height. (fig.2)




We then make diamond cover to match the size of the pad surfaces. (fig.3)

The aluminum gripper bar pads are then cleaned with glass beads, which give us a super clean surface for bonding the diamond covers to the pad



fig. 2

After allowing the bonding to cure over night and some cleaning around the diamond surface, the gripper bar is ready to ship. (fig.4)
 The price \$19.75 for each pad.



fFig. 4



fig. 3